

R

WORK AUTHORIZATION Contract AT-(29-2)-20 Job No. <u>942</u>	<i>Pacific Southwest Region</i> U.S. ATOMIC ENERGY COMMISSION PACIFIC PROVING GROUND	<u>5193</u> Serial Number 1000X 19907 H&N WORK ORDER NO. Job Folder No. <u>5155</u>
CONSTRUCTION/MAINTENANCE SERVICES		

TITLE DEACTIVATION AND RECOVERY OF EQUIPMENT AND CAMP FACILITIES

H & N IDENTIFICATION NO. 1000X 19907 LOCATION WOTHO

DATE ISSUED 7-29-58 DATE REQUIRED ASAP PRIORITY NORMAL

REQUESTED BY _____ TASK GROUP _____ PROJECT 80.0

COST CODE (H&N) _____ ACTION BY _____

APPLICABLE DRAWINGS 1612/100

DETAIL OF WORK TO BE PERFORMED

Furnish labor and material to deactivate and recover equipment and camp facilities site WOTHO.

BEST COPY AVAILABLE

APPROVED [Signature] DATE 7/29/58
 RESIDENT ENGINEER

All labor, material, installed equipment, equipment usage, concrete, and aggregate used in the performance of this work must be reported under this Work Order Number, with the description of the work performed in accordance with pages 3 and 14 thru 17 of the Holmes & Narver Foreman's Handbook.

Task Group Approval	A.E.C. Authorization	Holmes & Narver Approval
Date _____	<u>[Signature]</u> Date <u>7-30-58</u>	<u>[Signature]</u> Date <u>7/30/58</u>

DISTRIBUTION:

- | | |
|---------------------------------------|-------------------------------------|
| Engineering Division _____ (4) | Project Manager - H.O. _____ (1) |
| Construction Division _____ (30) | Project Controller - H.O. _____ (1) |
| Service Operations Division _____ (3) | Survey _____ (2) |
| Supply Division _____ (3) | Estimating _____ (2) |
| Accounting Division _____ (3) | Engr. Design _____ (1) |
| Chronological _____ (1) | Reporter _____ (1) |
| AEC Resident Engineer _____ (4) | Inspection _____ (4) |
| User _____ (1) | Test Lab _____ (1) |
| Project Engineer - H.O. _____ (1) | Property Section _____ (1) |
| Special Svcs _____ (1) | Safety Engineer _____ (1) |
| Comm _____ (2) | Radio _____ (2) |

REPRODUCTION FOR USE